



State of Connecticut

Department of Public Safety / Division of State Police

State Police Troop: KCase Number: DPS- 07-003038

ACCIDENT INFORMATION SUMMARY

Investigating Trooper: Mark Maynard # 653Date: 01-03-07Time: 1435

Notations:

Traffic: _____

Weather: _____

Lane _____ of _____

Direction of Travel: _____

N S E W

No. & Type of Veh's Involved: 3 vehicle Truck vs. Car vs. School Bus
(Passenger Car, Truck, Bus, Etc.)Related Information: # 710
(Pedestrian, Pole, Bridge Abutment, Etc.)Town / City: LEBANONLocation of Accident: Rte 207 @Utility Pole Name & Number (If Applicable): CLIP 710

Other (Specify): _____

Oper #1: Kulman Julie ADOB: 12-28-72Gender: ☐ M ☒ FAddress: 553 Exeter RdTown: LEBANONState: CTZip: 06249Oper. Lic. # 246269205Type: BState: CTOwner #1: Laidlaw Transit WncAddress: 5 Shelter Rock Rd Danbury, CTRegistration Plate: 95563State: CTMake: VolvoModel: RS 2708Year: 98VIN: 1HV0JAQN7WA082200Seatbelt(s): ☐ Yes ☐ No Airbag: ☐ Yes (Deployed ☐ Y ☐ N) ☐ No ☐ N/AInsurance Company: American Home AssuranceInsurance Policy #: CA 9799200Injuries: NoneVehicle Damage: RR bumper - minorVehicle Towed: ☒ No ☐ Yes

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Oper #2: Brown Kristin MDOB: 08-12-68Gender: ☐ M ☒ FAddress: 257 McCall RdTown: LEBANONState: CTZip: 06249Oper. Lic. # 208060576Type: 2State: CTOwner #2: Brown Craig JAddress: SAMERegistration Plate: 522 PNRState: CTMake: SaturnModel: SLYear: 02VIN: 1G8ZF52852Z176671Seatbelt(s): ☐ Yes ☐ No Airbag: ☐ Yes (Deployed ☐ Y ☐ N) ☐ No ☐ N/AInsurance Company: GEICOInsurance Policy #: 0224-93-32-00Injuries: Head to passVehicle Damage: REAR END LEFT & RIGHT SIDEVehicle Towed: ☐ No ☒ Yes, Desmond's Rte 16, Colchester

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Occupant(s): [Name / DOB / Address / Position in Veh]

Veh. #1 was a school bus traveling w/b Rte 207. Veh. #1 stopped at residence on Rte 207 to discharge passengers. Three veh.'s stopped behind the bus with Op. #2 being the last car in line. Veh. #3 also traveling w/b behind the bus failed to stop and substantially rear ended veh. #2. Veh. #2 shot ahead somehow missing the two veh's in front but went off the right hand side of the road striking a utility pole. Veh. #2 then glanced off the pole and shot back into the road striking the right rear of the school bus.

The only injury reported was a head injury to an infant traveling in the rear seat of veh. #2. She was transported to Hartford Hospital via Lifestar.

There were 28 students on the bus at the time of the accident. None were reported injured.

Anyone who may have witnessed the accident is asked to contact the Lebanon Resident Trooper's office at 860-642-7730. Police would specifically like to talk to the operators of two vehicles stopped behind the school bus at the time of the accident, but who immediately left the scene. One of them was reported as a smaller red 4 dr. compact style veh.

This investigation is: ☒ Open / Continuing ☐ Closed

MEDICAL ATTENTION:#1 Ambulance ☒ Yes, Company L.Y.F.D. ☐ NoPatient Name: Brown AnnabelleHospital: HartfordInjuries: head#2 Ambulance ☐ Yes, Company ☒ No

Patient Name: _____

Hospital: _____

Injuries: _____

#3 Ambulance ☐ Yes, Company ☐ No

Patient Name: _____

Hospital: _____

Injuries: _____

#4 Ambulance ☐ Yes, Company ☐ No

Patient Name: _____

Hospital: _____

Injuries: _____

FATALITIES: Do Not Release Unless Next of Kin Notified

Name: _____

Next of Kin Notified? ☐ Yes ☐ No

Name: _____

Next of Kin Notified? ☐ Yes ☐ No

Name: _____

Next of Kin Notified? ☐ Yes ☐ No

Name: _____

Next of Kin Notified? ☐ Yes ☐ No**ENFORCEMENT ACTION:**Arrested 14-227A - Prescott, James

Warned: _____

Arrested: _____

Warned: _____

Supervisor's Approval Required: Signature [Signature] # 227 Date 1-3-07